

CONSTRUCTION OBSERVATION REPORT #16

Date: October 21, 2016

Project Title: Arizona Way Bridge Construction Project

Record by: Blake Lettenmaier, PE, PLS

Project #: PW 2016-100

Contractor: KSH Construction Co.

Location: T 1N, R 10, SECTION 22, BA, Willamette Meridian,
Tillamook County, OR

Weather Conditions

Overcast

Temperature: 59 deg. F

Wind: 0-5 mph

Soil surface Condition

Moist

Summary

Contractor is not working today. Stream turbidity monitoring yielded the same turbidity level at upstream compliance location as that of the downstream compliance location. See compliance comparisons below. Straw waddle, straw check dams, straw mulch, silt fencing, bio bags, vegetative buffer and rock covered work areas are controls and practices implemented at the start of the work. See photos below.





Stream turbidity comparisons at compliance locations

END



Renews: 12-31-2016

c: *City of Garibaldi Staff*
File